

Extinguisher QTY-8

ETB - Automotive Service Technology Lab

BUILDING ETB138-1ST FLOOR ROOM NUMBERS



FILE NAME: LW138f1.dwg

LAST REVISION

12-08-08



- |           |                               |           |                    |
|-----------|-------------------------------|-----------|--------------------|
| ETB 100   | Lobby                         | ETB 103.4 | Engine Rebuild Lab |
| ETB 100.1 | Lobby                         | ETB 103.5 | Alignment Rack     |
| ETB 101   | Classroom                     | ETB 104   | Restroom           |
| ETB 102   | Auto Service Tech Evaluator   | ETB 105   | Material Storage   |
| ETB 103   | Automotive Service Technology | ETB 106   | Flammable Storage  |
| ETB 103.1 | Tool Storage                  | ETB 107   | Electric           |
| ETB 103.2 | Engine Storage                | ETB 108   | Mechanical         |
| ETB 103.3 | Flammable Storage             | ETB 109   | Data/Telecom.      |



Palm Beach State College  
 LAKE WORTH CAMPUS  
 BUILDING 138  
 EDUCATION & TRAINING CENTER  
 AreaGSF: 7577  
 AreaNSF: 7266