



PALM BEACH STATE COLLEGE PERSONAL PROTECTIVE EQUIPMENT (PPE) JOB HAZARD ASSESSMENT

Department: Facilities	Campus: All
Task: Replace a Light Bulb	
Job Title(s) Performing Task: Electrician, Maintenance Mechanic, Maintenance Worker	

Reviewed by Guy Clark, Lead Maintenance Mechanic, July 23, 2015

Task Step/Sub-Tasks	Hazard(s)	Recommended PPE (Bolded)/Controls
1. Utilize ladder or aerial lift device as necessary to access light/fixture/ballast. See also JHA "Use a Ladder" or JHA "Operate an Aerial Lift Device".	Falls from height	Ladder Safety training
		Use Personal Fall Arrest System when using aerial lift device.
2. Remove lens and lamp(s).	Falls from height	Ladder Safety training
	Cuts	Wear work gloves .
	Impact (from debris falling into eyes)	Wear safety glasses .
3. Replace lamp(s) and lens.	None foreseen	N/A
4. Test light by turning on light switch.	None foreseen	N/A

NOTE: Basic hazard categories include – **impact** (falling/flying objects, struck by), **falls from height**, **penetration** (sharp objects piercing foot/hand, other body parts), **compression** (roll-over or pinching), **cuts**, **burns**, **chemical exposure** (inhalation, ingestion, skin contact, eye contact or injection), **heat**, **extreme cold**, **harmful dust**, **noise**, **light (optical) radiation** (welding, brazing, cutting, furnaces, etc.), **ionizing radiation**, **non-ionizing (RF energy) radiation**, **electrical shock**, **ergonomics** (includes back strain or other strain due to lifting/stretching/awkward position or repetitive motion) and **biologic**.

CERTIFICATION: I certify that I have personally performed the above Job Hazard Assessment on the date indicated below. *This document is a Certification of the Hazard Assessment required by 29 CFR 1910.132(d)(2).*

Larry L. Leskovjan	<i>Larry L. Leskovjan</i>	July 23, 2015
Printed Name	Signature	Date